

GP9F-5: Genesi 90cm

Flush Mount 5 Gas Burner Hob



Introducing the Steel 5 gas burner cooktop providing a high quality cooking experience with features such as an ergonomic layout, flame failure and cast iron trivets. The thin design is specifically intended for narrow bench tops, helping to reduce overall bench space.

Features and Benefits:

Warranty	3 Years
Ergonomic Layout	The design of this hob makes it easy to use; with a Wok burner, this cook top allows a vast amount of different cooking styles.
5 Knob Controls	Making it easier and more accurate to control the flame.
Flame Failure	Stops the flow of gas if the flame is extinguished during the cooking process.
Cast Iron Trivets	Long lasting and easy to clean, the trivets and burners can be hand washed or put in the dishwasher.
MADE IN ITALY	Units are designed specifically for the Australian market and manufactured in Italy by dedicated boutique specialist manufacturer.


Distributed by Arisit Pty Ltd

40-44 Mark Anthony Drive, Dandenong South VIC 3175 Phone: 1300 762 219 Fax: 03 9706 6904 Website: www.arisit.com

www.steelbrand.com.au

GP9F-5: Genesi 90cm

Flush Mount 5 Gas Burner Hob



Model	GP9F-5
Control Panel	Stainless Steel with Plastic Knobs
Hob Surface	Brushed Stainless Steel
Hob Finish	Flush Mount
Mj/H Total Gas Consumption	43.6Mj/h
Far Left Burner	Rapid Burner = 15 Mj/h
Central Left Burner	Auxillary Burner = 1.7 Mj/h
Central Right Burner	Semi-Rapid Burner = 11 Mj/h
Far Right Burner	Auxillary Burner = 3.6 Mj/h
Flame Failure Device	YES
Product Dimensions	(W) 890mm x (D) 508mm x (H) 65mm
Cut Out Product Dimensions	(W) 860mm x (D) 480mm

WARNING: Technical specifications and product sizes can be varied by the manufacturer, without notice. Cut outs for appliances should only be physical product measurements. The above information is indicative only.

Distributed by Arisit Pty Ltd

40-44 Mark Anthony Drive, Dandenong South VIC 3175 Phone: 1300 762 219 Fax: 03 9706 6904 Website: www.arisit.com

www.steelbrand.com.au